



SEMS DocID

2317027

**ORIGINAL  
(Red)**

ROBERTSHAW CONTROLS COMPANY  
NEW STANTON DIVISION  
NEW STANTON, PENNSYLVANIA



Pittsburgh-Monroeville  
Pennsylvania 15146

GROUNDWATER INVESTIGATION  
INACTIVE PLANT DISCHARGE POND

PROJECT 79-204  
MARCH 1980

**ORIGINAL**  
**(Red)**

ROBERTSHAW CONTROLS COMPANY  
NEW STANTON DIVISION  
NEW STANTON, PENNSYLVANIA

GROUNDWATER INVESTIGATION  
INACTIVE PLANT DISCHARGE POND

GAI CONSULTANTS, INC.  
570 BEATTY ROAD  
MONROEVILLE, PENNSYLVANIA 15146

PROJECT 79-204

MARCH 1980

**ORIGINAL  
(Red)**

## TABLE OF CONTENTS

	<u>Page</u>
TABLE OF CONTENTS. . . . .	i
LIST OF TABLES . . . . .	ii
LIST OF FIGURES. . . . .	ii
INTRODUCTION . . . . .	1
GEOLOGIC SETTING . . . . .	3
GROUNDWATER FLOW CONDITIONS. . . . .	5
WATER QUALITY. . . . .	8
CONCLUSIONS. . . . .	10
RECOMMENDATIONS. . . . .	11
LIST OF REFERENCE. . . . .	12
TABLES	
FIGURES	
APPENDIX A - BORING LOGS	
APPENDIX B - WATER QUALITY ANALYSES	

**ORIGINAL  
(Red)**

## LIST OF TABLES

<u>Table</u>	<u>Description</u>
1	Well Monitoring Data
2	Concentrations of Mercury in Ground and Surface Water Samples and in Rock-Soil Samples
3	Description of Location and Feature Sampled for Rock-Soil Samples

## LIST OF FIGURES

<u>Figure</u>	<u>Description</u>
1	Location of the Robertshaw Controls, New Stanton Plant, Local Structural Geology, and Observed and Potential Groundwater Flow Paths
2	Monitoring Well Location Map
3	Cross-Sections Oriented with the Strike and Dip of the Underlying Rock Strata
4	Generalized Groundwater Flow Direction

## INTRODUCTION

The Robertshaw Controls, New Stanton Division plant located near Youngwood, Pennsylvania, is a manufacturer of thermostatic control devices. Figure 1 locates the plant relative to the general area. The production sequence produces wastewater which contains elevated levels of mercury. At present this mercury is removed from the wastewater prior to discharge to an unnamed stream located northeast of the plant. Previously, mercury removal was not practiced, and the discharge was routed through a small pond located at the plant. This produced a high mercury concentration within the pond and its sediments. The waste discharge to the pond was discontinued. Approximately one year later the mercury in the pond water was adsorbed onto powdered activated carbon (pac) and allowed to settle into the sediments. This procedure succeeded in substantially lowering the level of mercury in the pond, concentrating the mercury in the pond sediments. A mitigating factor reducing the possibility of mercury migration through the sediments into the local groundwater system is the presence of a bentonite liner beneath the pond. However, the absence of records concerning the extent and thickness of the bentonite layer and method of construction preclude conclusions as to the possible integrity of the bentonite liner.

Concern expressed by the Pennsylvania Department of Environmental Resources (DER) over the potential mercury contamination of local groundwater has prompted the present investigation. The purpose of this study is twofold, one to establish the hydraulic impact of the pond on the groundwater system and, second to assess to what degree, if any, mercury may have reached the groundwater. To accomplish these objectives a number of tasks were initiated including:

- o The establishment of a monitoring well program consisting of eight wells located strategically around the periphery of the pond (Figure 2). Five of the wells were extended to a depth sufficient to insure intersection with rock strata dipping beneath the pond. The remaining three wells were located to intercept and monitor any near surface downslope flow through either fill placed during site grading and/or unexcavated weathered shale.
- o The collection of updip and downdip ground and surface water samples to assess the extent of mercury seepage from the pond. Groundwater samples were secured from the wells located near the pond while surface water samples were taken at greater distances downdip from streams intercepting rock strata exposed beneath the pond.
- o The selective sampling of soil and rock specimens for evidence of adsorbed mercury to document the direction and depth of any previous pond discharge(s) to the groundwater. Samples were selected from rock cores and spoon samples taken at the site of the eight monitoring wells with subsequent analysis for mercury. Rock specimens for analysis were chipped from fractured and bedding surfaces.

The results of this study authorized by Robertshaw Controls are presented in the following sections.

## GEOLOGIC SETTING

The Robertshaw Controls Youngwood Plant is underlain by the Morgantown sandstone member of the Conemaugh Formation. In the area of study, the Morgantown is characterized by interbedded sandy and silty shales which are reported to dip north-northwest at approximately two degrees towards the Greensburg syncline which plunges gradually north-northeastward (Figure 1).<sup>1\*</sup> Boring logs taken during the coring and installation of the monitoring wells and presented in Appendix A, indicate a sequence of near surface silty shales underlain progressively at depth by fissile clay shales with very thin calcareous seams and limy claystone with calcium carbonate inclusions. Calculation of the strike and dip of these rock strata based on the elevation of the claystone contact indicates that locally these rock units are dipping N 15° E at approximately 2.2 degrees.

Figure 3 presents stratigraphic cross-sections drawn across the pond oriented along the strike and dip of the rock units. Cross-Section A-A' drawn down the dip of the inferred rock strata illustrates the potential for seepage to occur northeastwards down the dip of permeable rock strata. Previous boring logs prepared by Pennsylvania Drilling Company (9-16-58) describe a weathered rock mantle of from 8 to 14 feet thick on the preexcavation surface of this site. This unconsolidated mantle grades downwards from a highly weathered clayey silt surface soil to increasingly less weathered, yet highly fractured shale. High permeabilities and potential for subsurface seepage exists within the highly fractured shale which rests between impervious surface soil and intact bedrock. Remnants of this original

---

\* See list of references

weathered mantle remain along the eastern end of the pond as described in Boring Logs 5 and 6. Since the preexcavation surface originally sloped towards the east-northeast (Figure 2), it can be anticipated that the weathered mantle which formed parallel to that surface, likewise dips in that direction beneath the existing graded surface (Figure 3). Thus, any seepage occurring along the eastern edge of the pond would tend to flow readily downslope along the fractured shale zone as indicated in cross-section B-B' on Figure 3.



## GROUNDWATER FLOW CONDITIONS

Following a preliminary reconnaissance of the pond and its environs, eight points were selected for soil and rock sampling and subsequent well installation (Figure 2). Five deep well sites intended to intersect rock strata dipping beneath the pond were placed around the periphery of the pond and located to avoid interference from buried utility lines. Three additional shallow well sites were placed down gradient of the pond with respect to the existing and preexcavation surfaces to monitor near surface and perched waters.

Continuous samples of the unconsolidated surficial materials were obtained by repeatedly driving a split-barrel sampler from the surface until refusal with coherent rock. An NX core barrel was then used to secure a continuous rock core to the designated well depth. Upon completion of sampling, the hole was reamed with a six inch roller cone to facilitate installation of the 4-inch monitoring well. Installation of the deep wells was designed to restrict recharge to the intact rock strata avoiding recharge from any surficially fractured rock or soil zone. Shallow wells were installed to accept near surface or perched water while preventing direct surface seepage. Details of the installation sequence for the individual well is given with the respective boring logs in Appendix A. Following installation, the wells were pumped out and allowed to recharge naturally. Recharge in all wells was fairly rapid, with complete recharge occurring within two hours of evacuation in most instances. Prior to monitoring the elevation of the wells was surveyed (Figure 2) using the ground floor elevation of the office

building established on the Rust Engineering Grading Plans (April 28, 1966).

Table 1 summarizes the groundwater measurements made one week after installation of the wells and rechecked several weeks later. Though no substantial differences in groundwater elevations were observed over this brief period of time, it must be emphasized that fluctuations in the level of the groundwater may occur due to variations in rainfall, temperature, and other factors not evident at the time measurements were made and reported herein. This data was used to construct groundwater flow nets (Figure 4) with interpolation of equipotential and orthogonal flowlines from elevations of the groundwater surface observed in the individual wells.<sup>2</sup> Generalized groundwater flow in the vicinity of the pond for both shallow and deep well data is directed towards the east-northeast, approximating the original, preexcavation, downslope direction. A groundwater high recorded around well No. 2 and its likely downslope intersection with the present surface explains the saturated ground conditions noted in the field along the north end of the pond. Similarity between the flow nets constructed for the deep and shallow wells (Figures 4a and 4b) indicates the apparent absence of confined or perched waters at the site. This condition is not surprising considering the degree of fracturing observed in the underlying rock strata.

More detailed interpretations of the groundwater flow path around the pond can be made based on assumptions of the extent to which continuity exists between water in the pond and the surrounding groundwaters. If complete isolation of the pond water were

achieved, flowlines impinging on the pond liner system would be diverted around the pond as depicted in Figure 4c. If, on the other hand, there existed complete hydraulic continuity between the groundwater and water in the pond, then groundwater recharge of the pond would be expected along the western portion of the pond where groundwater elevations rise above the surface elevation of the pond. Concurrently discharge would occur along the eastern margin towards lower groundwater elevations on the downslope side of the pond as presented in Figure 4d. Noticeably, groundwater depths on the downslope discharge end of the pond tend to rise upwards towards the pond, intersecting with the surface elevation of the pond (Figure 3). This seems to suggest a degree of hydraulic continuity between these waters. If so two situations could exist. Either the structural integrity of the pond liner has been interrupted allowing direct flow through the pond liner or other groundwater conditions may exist. These include imperceptible fluctuations of the groundwater level which permit sufficient time for the pond waters to equilibrate with surrounding groundwater conditions, or the mere chance occurrence of equivalent groundwater levels. Verification of the degree of continuity could be obtained through an extended well monitoring program where fluctuations in the groundwater level are compared with fluctuations and response of water within the pond.

## WATER QUALITY

Table 2 summarizes the concentrations of mercury found in groundwater, surface water, and soil-rock samples (Appendix B). The concentration of mercury in the ground and surface waters, analyzed in this study, are within the acceptable (2 ppb) EPA tolerance level for primary drinking water.<sup>3</sup> In most instances the concentration of mercury is below the analytical detection limit of 0.5 ppb established for the cold vapor analysis. Groundwater samples were obtained for analysis after pumping of the individual wells produced a clear solution. Only in shallow well No. 5 was a clear water sample not obtained.

Surface water samples as shown in Figure 1 were obtained along two parallel northwest to southeast flowing streams which dissect down-dip rock strata exposed under the pond. The intent of these samples was to assess the impact, if any, of the potential downdip groundwater migration plume outlined in Figure 1. Samples S-2 and S-5 provide background water quality, upstream of anticipated bedrock seeps, whereas samples S-3, S-4, S-6, and S-7 provide downdip water quality. Of the downstream samples only Sample S-4, sampled approximately one mile downstream of the Robertshaw Controls Plant, showed any detectable indication of the presence of mercury. Barring analytical error, it is postulated that this downstream rise in mercury could result from either an earlier mercury discharge(s) now absorbed on sediments in the stream or from farming and trucking operations within the watershed. One other consideration is the near approach and overpassing of the stream by the Pennsylvania Turnpike near the sampling point. Sample S-3 obtained further

upstream and within one-quarter mile of the present plant discharge point, detected no measurable mercury.

The location, depth of sampling and origin of the respective rock-soil samples is summarized in Table 3. Control Sample RX-16 from an unaltered silty shale fracture stratigraphically above the elevation of the pond, as well as representative samples from the clay shale (RX-8) and limy claystone (RX-15) contained 1 ppm or less of Mercury (Table 2). Allowing for a normal degree of testing and sampling variance, (e.g., failure to obtain a good surface specimen from the rock chip), 4 of the 16 samples submitted for analysis appear to contain abnormally high mercury contents, higher even than that adsorbed within the bentonite liner. Three of these aberrant results were taken at varying depths in bore hole No. 6 while the fourth was from a near surface fracture in adjacent Bore Hole No. 8. Both sampling points are located on the eastern discharge end of the pond (Figure 4d) documenting prior continuity between the pond and the groundwater with a downslope component of flow in the direction of the preexcavation surface. If mercury were continuing to seep beyond these two bore points, it would be expected to show up in water samples (S-3 and S-4) taken in the nearby stream. Absence of substantive levels of mercury in these samples indicates that either the seepage front has passed since discontinuance of pond discharge or mercury has been adsorbed in passage through the rock strata.

## CONCLUSIONS

The groundwater surface in the vicinity of the Robertshaw Plant conforms to the general surface topography. Groundwater flow potential determined from well data indicates flowlines crossing the pond site from west to east, paralleling the downslope gradient of the preexcavation surface. Correspondence between groundwater elevations and the pond surface elevation, and evidence of previous mercury migration on rock surfaces along the downslope side of the pond, suggests probable hydraulic continuity between the pond and the surrounding groundwater. It is reasoned that former discharges of mercury from the pond into the surrounding rock strata would have been preferentially channeled downslope along the highly pervious fractured shales existing near the surface along the eastern end of the pond. From this zone of rapid seepage which parallels the preexcavation surface, discharge from the pond would penetrate to greater depths along occasional angular fracture planes in the underlying bedrock. No evidence was found, however, to substantiate the present downdip seepage of mercury along the hypothetical subsurface migration plume. Analysis of groundwater within the environs of the pond obtained from well samples and surface waters at greater distance down gradient, indicates no apparent present detrimental impact from previous mercury discharge(s) into the pond.

## RECOMMENDATIONS

The presence of adsorbed mercury on the clay mineral surfaces of the ponds bentonite liner and on rock fracture surfaces along the eastern discharge end of the pond provides the possibility of future desorption of mercury and possible groundwater contamination. Desorption of mercury from its presently held positions on mineral surfaces would require a change in the surrounding chemical environment. Changes which could induce desorption of mercury include natural or artificial alterations in the chemistry of the ponds water or long-term (greater than one year) weathering alterations along the present surface. Thus, continued well monitoring and sampling on a quarter year basis is recommended as a precautionary measure. The compilation of a continuous record of water quality around the pond could also prove beneficial in differentiating outside, extraneous inputs of heavy metals elsewhere in the surrounding watershed.

Respectfully submitted,  
GAI Consultants, Inc.

not responsive based on revised scope



## LIST OF REFERENCES

1. Department of the Interior, U.S.G.S., "Brownsville - Connellsville Pennsylvania Folio," #94, Washington D. C., 1903.
2. Davis, S. N., and DeWiest, R. J. M., Hydrogeology, John Wiley and Sons, Inc., New York, New York, 1966.
3. EPA, "National Interior Primary Drinking Water Regulations," Federal Register, Volume 40, #248, Washington, D. C., 1975.



Table 1

WELL MONITORING DATA  
(11/28/79)

Well No.*	Pumping Time		Total Minutes	pH	Temp. °C	Depth from Ground Surface		G. W. Elevation (ft above sea level)	
	Start	Finish				Start	Finish	(11/28/79)	(12/14/79)
1	12:31	12:40	9	7	8	3.75	4.25	1032.52	1032.46
2	11:40	11:48	8	7	9	1.67	2.50	1034.79	1034.76
3	11:25	11:35	10	7	8.5	0.67	2.50	1031.72	1031.75
4	10:13	10:21	8	7	9.5	3.90	5.0	1029.28	1029.40
5	10:53	11:17	24	7	10	5.00	5.83	1030.25	1030.25
6	10:37	10:45	8	7	8	6.00	7.0	1029.43	1029.69
7	12:07	12:15	8	7	8	2.72	2.75	1031.67	1031.25
8	11:56	12:01	5	7	7.5	5.08	5.50	1031.55	1031.55

\* See Figure 2 for well location and depth. Well numbers correspond to boring numbers.

ORIGINAL  
(Red)

Table 2

CONCENTRATIONS OF MERCURY IN GROUND AND SURFACE WATER  
SAMPLES AND IN ROCK-SOIL SAMPLES

	Groundwater Samples								Surface Water Samples						
	Monitoring Well								Pond	Stream 1+			Stream 2		
	<u>1</u>	<u>2</u>	<u>3</u>	<u>4</u>	<u>5</u>	<u>6</u>	<u>7</u>	<u>8</u>	<u>S-1</u>	<u>S-2</u>	<u>S-3</u>	<u>S-4</u>	<u>S-5</u>	<u>S-6</u>	<u>S-7</u>
Hg conc. (ppb*)	<.5	<.5	<.5	<.5	<.5	<.5	<.5	<.5	1.0	<.5	<.5	1.1	<.5	<.5	<.5

## ROCK-SOIL SAMPLES

	B.P. 1++				B.P. 2		B.P. 4		B.P. 6				B.P. 8				Bentonite Liner
	<u>RX-1</u>	<u>RX-2</u>	<u>RX-3</u>	<u>RX-4</u>	<u>RX-5</u>	<u>RX-6</u>	<u>RX-7</u>	<u>RX-8</u>	<u>RX-9</u>	<u>RX-10</u>	<u>RX-11</u>	<u>RX-12</u>	<u>RX-13</u>	<u>RX-14</u>	<u>RX-15</u>	<u>RX-16</u>	<u>S-8</u>
Hg conc. (ppm**)	2.0	<1.0	3.0	3.0	3.0	<1.0	3.0	1.0	6.0	11.0	<1.0	12.0	11.0	<1.0	<1.0	<1.0	2.2

\* Parts per billion. Limit of detection 0.5 ppb.

\*\*Parts per million. Limit of detection 1.0 ppm.

+See Figure 1 for stream location.

++Bore point numbers correspond to well numbers.

ORIGINAL  
(Red)

Table 3

## DESCRIPTION OF LOCATION AND FEATURE SAMPLED FOR ROCK-SOIL SAMPLES

<u>Sample No.</u>	<u>Bore Number</u>	<u>Depth</u>	<u>Sampled Feature</u>
RX-1	B.P. - 1*	5.0'	Very broken iron stained shale - bedding plane
RX-2	B.P. - 1	11.0'	Calcareous rock flour along fracture plane
RX-3	B.P. - 1	15.0'	Chips from highly fractured shale - claystone contact zone
RX-4	B.P. - 1	20.0'	Slickenside surface in claystone
RX-5	B.P. - 2	15.0'	Bedding fracture with seam of carbonates
RX-6	B.P. - 2	17.5'	Fractured surface (30°) with carbonate coating
RX-7	B.P. - 4	9.0'	Fractured surface (60°) with iron staining
RX-8	B.P. - 4	17.5'	Fractured iron stained surfaces
RX-9	B.P. - 6	4.0'	Highly weathered shale residuum
RX-10	B.P. - 6	9.0'	Fragmented iron stained shale zone


ORIGINAL  
(Red)

Table 3  
(Continued)

<u>Sample No.</u>	<u>Bore Location</u>	<u>Sampling Depth</u>	<u>Sampled Feature</u>
RX-11	B.P. - 6	13.0'	Very broken iron stained shale - bedding surface
RX-12	B.P. - 6	20.5'	Slickenside surface in claystone
RX-13	B.P. - 8	2.0'	Fractured surface (60°) with iron staining
RX-14	B.P. - 8	16.5'	Very broken claystone fragment
RX-15	B.P. - 8	20.5'	Slickenside surface in claystone
RX-16	B.P. - 2	2.5'	Unaltered silty-shale surface

\*Bore point or well number.

ORIGINAL  
(Red)



ORIGINAL  
(Red)

SCHEDULE OF BORINGS		
BORING NUMBER	GROUND SURFACE ELEVATION (11/22/79)	DEPTH (FT.)
1	1036.2	21.2
2	1036.4	20.8
3	1032.4	7.8
4	1033.2	21.0
5	1035.3	7.5
6	1035.4	21.0
7	1034.4	7.4
8	1036.6	21.0
TOTAL FOOTAGE		127.7

### LEGEND

- ⊕ MONITORING WELL LOCATION
- - -1030- ORIGINAL GROUND SURFACE CONTOURS
- 1030— EXISTING GROUND SURFACE CONTOURS
- - - EXISTING FEATURES
- ... EDGE OF POND

NOTE: FOR SECTIONS A-A' AND B-B' SEE DRAWING 79-204-B2.

POND ELEVATION AT 1032.1 FEET AMSL ON 11-28-79.

Figure 2


**gai**  
CONSULTANTS, INC.  
Engineers • Geologists • Planners  
Environmental Specialists  
570 Beatty Rd. • Pittsburgh,  
Monroeville, Pa. 15146  
412-342-8530

### MONITORING WELL LOCATION MAP

ROBERTSHAW CONTROLS COMPANY  
NEW STANTON DIVISION  
NEW STANTON, PENNSYLVANIA

DWN. [REDACTED] CHKD. \_\_\_\_\_  
APPD. \_\_\_\_\_ DATE \_\_\_\_\_  
SCALE: 1" = 200'  
DRAWING NUMBER  
79-204-B1









TION SURFACE +

ORIGINAL  
(Red)



Rock Strata \*

SURFACE +



f Rock Strata \*

Figure 3

**gai**  
CONSULTANTS, INC.  
Engineers • Geologists • Planners  
Environmental Specialists  
570 Beatty Rd. • Pittsburgh,  
Monroeville, Pa. 15146  
412-342-6530

CROSS SECTIONS ORIENTED WITH THE STRIKE  
AND DIP OF THE UNDERLYING ROCK STRATA


ROBERTSHAW CONTROLS COMPANY  
NEW STANTON DIVISION  
NEW STANTON, PENNSYLVANIA

DWN. ☒ CHKD. ☐  
APPD. ☐ DATE ☐  
SCALE: AS SHOWN  
DRAWING NUMBER  
79-204-B2

REV




Elevation Above  
Sea Level (Feet)



Section  
Drawn with Dip

Elevation Above  
Sea Level (Feet)



Section  
Drawn with Dip

NOTES:

- \* FOR TRANSECT LOCATION SEE  
DRAWING 79-204-B1.
- + SURFACES BASED ON RUST  
ENGINEERING DRAWING (4/28/66)

SCALE: 1" = 50' HORIZONTAL  
1" = 20' VERTICAL

LEGEND



UNWEATHERED BEDROCK SURFACE



POTENTIAL SEEP DIRECTION



BORE POINT AND MONITORING WELL  
LOCATION

ORIGINAL  
(Red)






Figure 4b - Deep Well

NOTE: \* REFERENCE DRAWING 79-204-B11

Figures 4a and 4b

 <b>CONSULTANTS, INC.</b> Engineers • Geologists • Planners Environmental Specialists 570 Beatty Rd. • Pittsburgh, Monroeville, Pa. 15146 412-242-6530	GENERALIZED GROUNDWATER FLOW DIRECTION		DWN. <span style="background-color: black; color: black;">[redacted]</span>	CHKD. _____
	ROBERTSHAW CONTROLS COMPANY NEW STANTON DIVISION NEW STANTON, PENNSYLVANIA		APPD. _____ DATE _____	
			SCALE: 1" = 400'	
			DRAWING NUMBER 79-204-B3	
				 REV

ORIGINAL  
(Red)




Figure 4a - Shallow Well

LEGEND

- |   |  |
|---|--|
| ----- Hydraulic Equipotential Contour                 | ----- Existing Ground Surface Contours * |
| ..... Projection of Equipotential Contour across Pond | ----- Original Ground Surface Contours * |
| ➔ Direction of Groundwater Flow                       | ----- Edge of Pond *                     |
| ----- Existing Features *                             | • Monitoring Well Location               |

ORIGINAL  
(Red)






Figure 4d – Shallow Groundwater Flow Pattern  
Assuming Hydraulic Continuity with  
Pond

Figure 4c and 4d

 <b>CONSULTANTS, INC.</b> Engineers • Geologists • Planners Environmental Specialists 570 Beatty Rd., • Pittsburgh, Monroeville, Pa. 15146 412-842-6530	GENERALIZED GROUNDWATER FLOW DIRECTION		DWN. <input checked="" type="checkbox"/> <small>not responsive base</small>	CHKD. <input type="checkbox"/>
	ROBERTSHAW CONTROLS COMPANY NEW STANTON DIVISION NEW STANTON, PENNSYLVANIA		APPD. <input type="checkbox"/>	DATE <input type="checkbox"/>
			SCALE: 1" = 400'	
			DRAWING NUMBER 79-204-B4	
				 REV

ORIGINAL  
(Red)




Figure 4c - Shallow Groundwater Flow Pattern  
Assuming No Hydraulic Continuity  
with Pond



ENVIRONMENTAL RESOURCES  
CONSULTANTS, INC.

PROJECT NO. 79-204

BORING NO. \_\_\_\_\_

11/20/79 HRS 3.4'

DATE 11/16/79 FIELD ENGINEER

PAGE NO. 1 OF 1

REMARKS:\*\*\* CONTINUOUS SPLIT SPOON SAMPLE TO 4.3' (REFUSE), HOLE CLEANED  
w/ HOLLOW STEM AUGERS, 6" CASING SET TO 2' PROJECT NO. 79-204  
 \*\* POCKET PENETROMETER READINGS BORING NO. 1  
 \*\*\* METHOD OF ADVANCING AND CLEANING BORING



ORIGINAL  
(Red)PROJECT ROBERTSHAW MONITORING WELLPROJECT NO. 79-204ELEVATION 1036.4 GWL 0 HRS 0.8'BORING NO. 215 HRS 1.4'DATE 11/15/79 FIELD ENGINEER [REDACTED]PAGE NO. 1 OF 1

DEPTH FEET	BLOWS PER SIX INCHES OR CORE RECOVERY/RUN	SAMPLE NO., TYPE & RECOVERY OR % ROCK RECOVERY	WELL PACING SEQUENCE CASING BLOWS	DESCRIPTION				USCS OR ROCK BROKENNESS	REMARKS**
				PROFILE	SOIL DENSITY- CONSISTENCY OR ROCK HARDNESS	COLOR	MATERIAL CLASSIFICATION		
1	2	3	4	5	6	7	8	9	10
1	31	0 S-1	↑	VERY MOSE	BROWN	MOIST SANDY-SILT TOPSOIL/FILL	ML		20% WEATHERED SHALE FRAGMENTS
2	45	0 S-2	↑	SOFT	GRAY	SLIGHTLY MOIST WEATHERED FESSILE SHALE	V.BR		BROKE EVERY 1/16" ALONG BEDDING PLATES
3		0.9% 11.0	↑						
4			↑	MED. SOFT	BLACK	SILTY SHALE w/ FEW VERY THIN	V.BR		
5		4.7% 5.0	↑				CALCAREOUS SILTSTONE		FRACTURED ALONG
6		16 MIN	↑				SEAMS		HORIZONTAL BEDDING
7			↑						AND AT ANGLE TO
8			↑						BEDDING, SURFACES
9			↑	MED. HARD	DARK GRAY			BR	SMOOTH, UNALTERED
10		4.4% 5.0	↑						THOUGH HAVING
11		15 MIN	↑						CARBONATE REACTION
12			↑						SHALE NON-REACTIVE
13			↑						
14			↑	MED. HARD	DARK GRAY			BR	
15		5.0% 5.0	↑						
16		15 MIN	↑						
17			↑						
18			↑						INCREASE IN
19		3.3% 3.3	↑	MED. HARD	DARK GRAY	CLAY SHALE w/ SOME VERY THIN	BR.		NUMBER OF CAL-
20		4 MIN.	↑			CALCAREOUS SEAMS			CAREOUS SEAMS &
21			↑						BEDDING PLANE FRACTURE
22			↑						
							CORING COMPLETED AT 20.8 FT.		WELL PUMPED -
							HOLE REAMED TO 6" DIA. TO DEPTH OF		OUT AFTER
							20.4 FT.		INSTALLATION
							4" DIA. PVC STICK-UP 1.8 FT. (TOTAL		11/21/79
							LENGTH 22.0 FT)		

REMARKS\*\*\* CONTINUOUS SPLIT SPOON SAMPLE TO 1.5' (REFUSAL), HOLE CLEANED  
w/ HOLLOW STEM AUGER, 6" CASING SET TO 2.0'PROJECT NO. 79-204BORING NO. 2

\*\* POCKET PENETROMETER READINGS

\*\*\* METHOD OF ADVANCING AND CLEANING BORING



**RADIAN**  
CONSULTANTS, INC.

PROJECT NO. 79-204  
BORING NO. 3

PAGE NO. 1 OF 1

REMARKS: CONTINUOUS SPUN SAMPLE TO 1.4 FT. (REFUSAL), 6" CASING SET TO 1.5 FT. PROJECT NO. 79-204

PROJECT NO. 79-204  
BORING NO. 3



ORIGINAL  
(Red)



PROJECT ROBERTSHAW MONITORING WELL  
ELEVATION 1033.2 GWL 0 HRS @ SURFACE

PROJECT NO. 79-204  
BORING NO. 4

DATE 11/20/79 FIELD ENGINEER [REDACTED]  
HRS not responsive based on revised scope

PAGE NO. 1 OF 1

DEPTH FEET	BLOWS PER SIX INCHES OR CORE RECOVERY/RUN	SAMPLE NO., TYPE & RECOVERY OR & ROCK RECOVERY	WELL PICKING SURFACE CASING-BLOWS	DESCRIPTION				USCS OR ROCK BROKENNESS	REMARKS**
				PROFILE	SOIL DENSITY- CONSISTENCY OR ROCK HARDNESS	COLOR	MATERIAL CLASSIFICATION		
1	2	3	4	5	6	7	8	9	10
1	10	0 S-1			VERY LOOSE	BROWN	MOIST SANDY-SILT TOPSOIL/FILL	ML	5% WEATHERED C.F.
2	27	0 S-2			MED. DENSE	VEL. OR TO GRAY	SLIGHTLY MOIST HIGHLY WEATHERED SHALE RESIDUAL		Fe <sub>2</sub> O <sub>3</sub> STAINING ON FLATE SURFACES
3	54	0 S-3			DENSE				
4					MED. SOFT	DARK GRAY	SILTY SHALE W/ FEW VERY THIN CALCAREOUS SEAMS	BR	
5		4.4/5.0							FRACTURED ALONG HORIZONTAL BEDDING PLANES AND AT ANGLE (45°-60°) TO BEDDING.
6									
7									
8									
9					MED. HARD	DARK GRAY		BR	SURFACES SMOOTH W/ Fe <sub>2</sub> O <sub>3</sub> COATING.
10		5.0/5.6							
11		22 MIN							
12									
13									
14		5.0/5.6			MED. HARD	DARK GRAY		BR	
15		20 MIN							
16									
17									
18							CLAY SHALE W/ SOME VERY THIN CALCAREOUS SEAMS		
19		3.3/3.5			MED. HARD	DR. GRAY		BR	
20		15 MIN							
21									
22							CORING COMPLETED AT 21.0 FT HOLE REAMED TO 6" DIA. TO DEPTH OF 21.0 FT. 4" DIA PVC STICK-UP 1.3 FT (TOTAL LENGTH 22.0 FT.)		WELL PUMPED OUT AFTER INSTALLATION 11/21/79

REMARKS\*\*\* CONTINUOUS SPLIT SPON SAMPLE TO 2.4 FT (REFUSAL), HOLE CLEANED  
W/ HOLLOW STEM AUGER, 6" CASING SET TO 2.1 FT. PROJECT NO. 79-204  
\*\* POCKET PENETROMETER READINGS BORING NO. 4  
\*\*\* METHOD OF ADVANCING AND CLEANING BORING





**RMC**  
CONSULTANTS, INC.

BORING NO. 6

PAGE NO. 1 OF 1

REMARKS: CONTINUOUS SPLIT SPOON SAMPLE TO 4.4' (REFUSAL), HOLE CLEANED  
W/ HOLLOW STEM AUGER, 6" CASING SET TO 2.0' PROJECT NO. 79-204

- \* POCKET PENETROMETER READINGS
- \*\*\* METHOD OF ADVANCING AND CLEANING BORING

BORING NO. 6



CONSULTANTS, INC.

PROJECT NO. 79-204

BORING NO. 7

not responsive based on revised scope

PAGE NO. 1 OF 1

not responsive based on revised scope

PROJECT NO. 79-204

BORING NO. \_\_\_\_\_

- ※ POCKET PENETROMETER READINGS
- ※※ METHOD OF ADVANCING AND CLEANING BORING



PAGE NO. 1 OF 1

REMARKS: CONTINUOUS SPLIT SPOON SAMPLE TO 1.5 FT. HOLE CLEANED W/  
HOLLOW STEM AUGER, 6" CASING SET TO 1.5 FT. PROJECT NO. 79-204

BORING NO. 8





PENN ENVIRONMENTAL CONSULTANTS, INC.  
FORT PITT PROFESSIONAL BUILDING  
1517 WOODRUFF STREET  
PITTSBURGH, PA. 15220  
412-331-1133

ORIGINAL  
(Red)

GENERAL LABORATORY REPORT

A. CLIENT		GAI Consultants, Inc.		B. PEC PROJECT NO. 059-3767	
C. SAMPLE SOURCE AND DATE					
See below					
D. DATE ANALYZED 11-21-79		E. CHEMIST		F. TYPE OF SAMPLE	
				G. SAMPLE NO. See below	

ANALYSIS

RESULTS

Sample	PEC #	Hg
S-1 Pond 11/19	50297	1.0 ug/l
S-2	50298	<.5 ug/l
S-3	50299	<.5 ug/l
S-4 11/20	50300	1.1 ug/l
S-5	50301	<.5 ug/l
S-6	50302	<.5 ug/l
S-7	50303	<.5 ug/l
S-8 Pond Bentonite	50304	2.2 mg/kg

REMARKS:

3 ug/l 11-21-79

